



ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್‌ರವರ ಕಛೇರಿ, ಮೈಸೂರು ವಿಭಾಗ, ಮೈಸೂರು.

www.eepwdmys21@gmail.com

ದೂರವಾಣಿ ಸಂಖ್ಯೆ/ಫ್ಯಾಕ್ಸ್ ನಂ: 0821 2420810

ಸಂಖ್ಯೆ :ಕಾಇಂ:ಲೋಇ:ಮೈವಿಮೈ: ಸ ಇಂ-4: ಕಟ್ಟಡ ಸುರಕ್ಷತೆ: 2024-25

3449-3450

ಇವರಿಗೆ :

35/09/2024

ಪ್ರಾಂಶುಪಾಲರು,
ಡೆಲ್ಲಿ ಪಬ್ಲಿಕ್ ಸ್ಕೂಲ್,
ಸರ್ವೆ ನಂ. 11/1, ಭೂಗತಗಳ ವಿಲೇಜ್,
ವರುಣಾ ಹೋಬಳಿ,
ಮೈಸೂರು 570 011.

ಮಾನ್ಯರೇ,

ವಿಷಯ: ಮೈಸೂರು ತಾಲ್ಲೂಕು, ಭುಗತಹಳ್ಳಿ ಗ್ರಾಮ, ಬನ್ನೂರು ರಸ್ತೆಯಲ್ಲಿರುವ ಡೆಲ್ಲಿ ಪಬ್ಲಿಕ್ ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವ ಬಗ್ಗೆ.

- ಉಲ್ಲೇಖ ; 1. ಪ್ರಾಂಶುಪಾಲರು, ಡೆಲ್ಲಿ ಪಬ್ಲಿಕ್ ಶಾಲೆ, ಬನ್ನೂರು ರಸ್ತೆ, ಭುಗತಹಳ್ಳಿ ಗ್ರಾಮ, ಮೈಸೂರು, ಇವರ ಮನವಿ ಪತ್ರ ದಿನಾಂಕ 23.11.2023.
2. ಸಕಾಇಂ., ನಂ.2, ವಿಶೇಷ ಉಪ-ವಿಭಾಗ, ಮೈಸೂರು, ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ 674 ದಿನಾಂಕ 20.12.2023.
3. ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ ಲೋಇ:59:ಬಿಇಡಿ:2019 ದಿನಾಂಕ 06.05.2022.
4. ಸಕಾಇಂ., ನಂ.2, ವಿಶೇಷ ಉಪ-ವಿಭಾಗ, ಮೈಸೂರು, ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ 274 ದಿನಾಂಕ 26.07.2024.
5. ಈ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ 2238 ದಿನಾಂಕ 02.08.2024.
6. ಸಕಾಇಂ., ನಂ.2, ವಿಶೇಷ ಉಪ-ವಿಭಾಗ, ಮೈಸೂರು, ಇವರ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ 403 ದಿನಾಂಕ 17.09.2024.
7. ಈ ಕಛೇರಿ ಪತ್ರ ಸಂಖ್ಯೆ 3406-3407 ದಿನಾಂಕ 23.09.2024

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಮೈಸೂರು ತಾಲ್ಲೂಕು, ಭುಗತಹಳ್ಳಿ ಗ್ರಾಮ, ಬನ್ನೂರು ರಸ್ತೆಯಲ್ಲಿರುವ ಡೆಲ್ಲಿ ಪಬ್ಲಿಕ್ ಶಾಲಾ ಕಟ್ಟಡವನ್ನು ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.2, ವಿಶೇಷ ಉಪವಿಭಾಗ, ಮೈಸೂರು ರವರು ಪರಿವೀಕ್ಷಣೆ ಮಾಡಿದ್ದು, **Build point Constructions and Technologies, Gangothri Layout, Mysore** ರವರು ISO/IEC National Building Code 2016 Group B (Sub Division B1 and B2) Education Building ರನ್ವಯ NDT test & Structural Stability Certificate ಹಾಗೂ ತಾಂತ್ರಿಕ ವರದಿಗಳೊಂದಿಗೆ ನಿಗದಿತ ನಮೂನೆಯಲ್ಲಿ ವರದಿಯನ್ನು ಸಲ್ಲಿಸಿರುತ್ತಾರೆ. ಸದರಿ ವರದಿಯನ್ನು ದಿನಾಂಕ 26.07.2024 ರಂದು ಸ್ಥಳ ಪರಿಶೀಲಿಸಿ ಉಲ್ಲೇಖ (2) ರಲ್ಲಿ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.2 ವಿಶೇಷ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ರವರು ದೃಢೀಕರಿಸಿರುತ್ತಾರೆ.

ಸದರಿ ಕಟ್ಟಡವನ್ನು ದಿನಾಂಕ 26.07.2024 ರಂದು ಭೌತಿಕವಾಗಿ ಪರಿಶೀಲಿಸಲಾಗಿ, ಕಟ್ಟಡವು ನಾಲ್ಕು ಅಂತಸ್ತುಗಳಿದ್ದು, ಸದರಿಯವರು ನೀಡಿರುವ ದಾಖಲಾತಿಗಳ ಪ್ರಕಾರ ಕಟ್ಟಡವು 2014 ಕ್ಕೆ ಪೂರ್ಣಗೊಂಡಿದ್ದು, ಕಾಲೇಜು ಕಟ್ಟಡವು ಎನ್.ಡಿ.ಟಿ. ವರದಿಗಳಂತೆ ಸುರಕ್ಷಿತವಾಗಿದ್ದು, ಕಟ್ಟಡವು ಉಪಯೋಗಕ್ಕೆ ಯೋಗ್ಯವಾಗಿರುತ್ತದೆ ಎಂದು **Buildpoint constructions and Technologies, Gangothri Layout, Mysore,**


ರವರು ಹಾಗೂ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.2 ವಿಶೇಷ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿರುವ ಬಗ್ಗೆ ಹಾಗೂ ಎಲ್ಲಾ ರೀತಿಯ ಸೌಲಭ್ಯಗಳನ್ನು ಹೊಂದಿರುವ ಬಗ್ಗೆ ದೃಢೀಕರಿಸಿರುತ್ತಾರೆ.


ಮುಂದುವರೆದು, ಕಟ್ಟಡದ ಸುರಕ್ಷತೆಗೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು, ನಂ.2, ವಿಶೇಷ ಉಪವಿಭಾಗ, ಮೈಸೂರು, ರವರು ಉಲ್ಲೇಖ ಪತ್ರದಲ್ಲಿ ಕಟ್ಟಡದ ಕಾಂಕ್ರೀಟ್ ಸದೃಢತೆಯ ಬಗ್ಗೆ **Buildpoint Constructions and Technologies, Gangothri Layout, Mysore** ಇವರ Physical observation & Accordingly necessary field Tests ಪರೀಕ್ಷೆಗಳನ್ನು ಕೈಗೊಂಡು, ಸಮಾಲೋಚಕರೊಂದಿಗೆ ಉಪವಿಭಾಗದ ತಾಂತ್ರಿಕ ವರ್ಗವು ನಡೆಸಿರುವ ಪರೀಕ್ಷೆಯ ವರದಿಯಂತೆ ಕಟ್ಟಡವು ಸದೃಢತೆಯಿಂದ ಇರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆ ಎಂದು ವರದಿ ಮಾಡಿರುತ್ತಾರೆ.

- Recognizance, visual inspection of Building-cracks, distress, dampness etc. ಪರೀಕ್ಷೆಯನ್ನು **Buildpoint Constructions and Technologies, Gangothri Layout, Mysore** ರವರ ಜೊತೆ ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆಯ ತಾಂತ್ರಿಕ ತಂಡದೊಂದಿಗೆ ಕೈಗೊಳ್ಳಲಾಗಿರುತ್ತದೆ.
- Form for Certificate for Structural Design Sufficiency ಪ್ರಮಾಣ ಪತ್ರವನ್ನು **Buildpoint Constructions and Technologies, Gangothri Layout, Mysore** ರವರು ನೀಡಿರುತ್ತಾರೆ.

ಸದರಿ ಸಂಸ್ಥೆಯವರು ಕರ್ನಾಟಕ ಸರ್ಕಾರದ ಸುತ್ತೋಲೆ ಸಂಖ್ಯೆ ಲೋಇ:59:ಬಿಇಡಿ:2019 ದಿನಾಂಕ 06.05.2022. ರಂತೆ ಸದರಿ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಪಡೆಯಲು ನಿಗದಿಪಡಿಸಿರುವ ಶುಲ್ಕವಾದ ರೂ. 1,000.00 ಗಳನ್ನು ಲೆಕ್ಕಶಾಖೆಗೆ ಪಾವತಿಸಿರುವುದರಿಂದ, ಮತ್ತು **Buildpoint constructions and Technologies, Gangothri Layout, Mysore**, ರವರು ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ನೀಡಿರುವ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಸಲ್ಲಿಸಿರುವುದರಿಂದ, ಹಾಗೂ ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ನಂ.2, ವಿಶೇಷ ಉಪವಿಭಾಗ, ಮೈಸೂರು ರವರು ದಿನಾಂಕ 26.07.2024 ರಂದು ಭೌತಿಕವಾಗಿ ಸ್ಥಳ ಪರಿವೀಕ್ಷಣೆ ಮಾಡಿ ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿದ್ದು, ಪ್ರಸ್ತುತ ಕಟ್ಟಡವು ಉಪಯೋಗಕ್ಕೆ ಯೋಗ್ಯವಾಗಿರುತ್ತದೆ ಎಂದು ದೃಢೀಕರಿಸಿರುವುದರಿಂದ, ಪ್ರಸಕ್ತ ಶೈಕ್ಷಣಿಕ ಸಾಲಿಗೆ ಕಟ್ಟಡ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು (Building Safety Certificate) ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,


ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ
ಮೈಸೂರು ವಿಭಾಗ, ಮೈಸೂರು.



Government of Karnataka
Public Works Department
Office of the Executive Engineer
Mysore Division, Mysore.

Email: eepwdmys21@gmail.com

Phone: 0821 -2420810

Letter No. AE-4/PWD/2024-25

3449-3450

Date: 25/09/2024

To:

The Principal,
Delhi Public School
Survey No. 11/1, Bhugathgalli Village,
Varuna Hobli
Mysore – 570011.

Respected Sir,


Subject: Regarding building safety certificate and structural strength of the building.

References:

1. Request from the Principal, Delhi Public School, Mysore, Bhugathgalli Village, Mysore, dated 23.11.2023
2. Government Order No. 674 dated 20.12.2023
3. Government Order No. 59:BED:2022 dated 06.05.2022
4. Government Order No. 274 dated 26.07.2024
5. PWD Letter No. 2238 dated 02.08.2024
6. Government Order No. 2, Special Sub-Division, Mysore, their Office Letter No. 403 dated 17.09.2024
7. This office letters No. 3406–3407 dated 23.09.2024

As per the above references, the Delhi Public School building located in Bhugath Halli Village, Bannur, Road, Mysore Taluk was inspected by the Assistant Executive Engineer, No. 2 Special Sub-Division, Mysore. Buildpoint Constructions and Technologies, Gangothri Layout, Mysore carried out the NDT test and Structural Stability Certificate and submitted the report in the prescribed format along with the technical reports. The said building was inspected on 26-07-2024 and confirmed in reference by the Assistant Executive Engineer, Public Works Department No. 2 Special Sub-Division, Mysore.

The said building was inspected on 26-07-2024 and the building has four floors. According to the documents provided by the said person, the building was completed in 2014. The college building is safe as per the NDT reports and the building is fit for use. Buildpoint Constructions and Technologies, Gangothri Layout, Mysore and Assistant Executive Engineer Public Works Department No. 2 Special Sub-Division, Mysore have confirmed that the building is safe and has all kinds of facilities.




No. of Corrections

Furthermore, in the reference letter of Assistant Executive Engineer No. 2 Special Sub-Division Mysore regarding the safety of the building, the strength of the building concrete has been stated in the report of the test report conducted by Buildpoint Constructions and Technologies, Gangothri Layout, Mysore.

1. Recognition and visual inspection of the building, cracks, distress, dampness, etc. was conducted by Buildpoint Constructions and Technologies, Gangothri Layout, Mysore along with the technical team of the Public Works Department.
2. The Form for Certificate of Structural Design Sufficiency was issued by Buildpoint Constructions and Technologies, Gangothri Layout, Mysore.

As per the government circular No: ESE:59:BED:2019 dated 06-05-2022. The said institution has paid the prescribed fee of Rs. 1,000 to the Accounts Department for obtaining the said Building Safety Certificate as per the Karnataka Government Circular No. Date and since Buildpoint Constructions and Technologies, Gangothri Layout, Mysore has submitted a certificate stating that the building is structurally safe and since Assistant Executive Engineer, Public Works Department No. to Special Sub-Division, Mysore has physically inspected the site on the date and confirmed that the building is safe and the present building is fit for use, the (Building Safety Certificate) has been issued for the current academic year.


Executive Engineer
Public Works Department
Mysore Division,
Mysore



TRANSLATED this documents from
the Original in... Kannada
language to ... English
and the translation Verified by me.

NOTARY, MYSORE DISTRICT

13 JUN 2025



No. of Corrections Nil